

- Septic tank backing up AGAIN; due to wet weather

Wet area near generator at corner of fire station addition.



Close-up of wet spot.

Wayland McFarland septic service - tel:919-383-1015



- Side Porch/Walkway/Ramp need to remove and/or replace

















- Front Retaining wall is cracked



- Porch is settling and causing pillars to separate from the roof
- Front Porch Column noted to be separating from ceiling; perhaps due to settling of porch





Separation at this time is approximately 1.5 cm (or 5/8 inches). This is the column on the Whitfield Road side of the building.



Column separation on the opposite side of the front porch. This is barely 2 cm or 1/16/ inch at this time.





Small crack in foundation under front porch. There is very little separation of shifting visible at this time but this should be monitored.

- Add gravel to eliminate the bog at the front of the building
- Front Ramp Railing is very shaky
- Roof Edge & Gutters - damage to the edge of the roof and gutters on the back of the building
- Soffit (vinyl) needs repair at backdoor
- Back Ramp needs to be replaced or removed.





- Regrade back yard to take water away from building
- Kitchen needs to be repainted for HEALTH REASONS
- Updating the Meeting room lighting
- Siding needs washing, no need to replace but it could use some attention to look a lot better
- Fire alarm system will be redone for the entire building and NHIA will need to pay for our part
- Updating the Meeting room walls
- Updating the Meeting room flooring
- Inside bathrooms are in need of updating
- Front shrubbery looking pretty bad, probably should be replaced
- Folding chairs need upgrading
- New pots and pans need upgrading

- Projector and Screen